



**Advisory # 2019-A-024**

**Subject: New Apron Paint Markings – Gates 161, 161A, 163, 165, 165A, new one-way connection road between Gate 157/161 and 163/165.**

**From:** Aviation Services

**Contact:** Dean Wright, Dean.Wright@gtaa.com, 416-776-4062

**Date:** May 29, 2019

Please be advised that the next phase of work will begin at Terminal 1 to support the Code D and E aircraft on Gates 161A and 165A. Gate 163 will be reconfigured to accommodate a full Code C aircraft mix. VDGS at each gate will be modified accordingly.

This phase consists of line changes and painting and no construction is required. The existing two-way connection road between head of stand and tail of stand at gate 165/167 will be split into two separate one-way connection road at Gate 157/161 and Gate 163/165 (see attached map).

A Sierra line, 7S, will be added between taxilane 7 and 8 to assist code E aircraft taxiing to gate 151 and 161A.

This advisory outlines the general impacts to the surrounding area for this phase of the project. Individual gate closures will be coordinated as work is anticipated to take several weeks and is weather dependent.

An updated gate mix resulting from this work will be issued for the new gate configurations.

Please see the below showing new paint at the redesigned gates.

Toronto Pearson Advisory

: New Apron Paint Markings – Gates 161, 161A, 163, 165, 165A, new one-way connection road between Gate 157/161 and 163/165.

May 29, 2019




Fig. 1 – Final configuration

: New Apron Paint Markings – Gates 161, 161A, 163, 165, 165A, new one-way connection road between Gate 157/161 and 163/165.

May 29, 2019




Fig. 2 – Operation sequence